

Photo #1: Tubidity caused by dredging in vicinity of Rackham Cay – June 11, 2002



Photo #2: Turbidity caused by dredging – June 14, 2002



Photo #3: Silt screen on eastern side of Rackham Cay – June 16, 2002



Photo #4: Turbidity in vicinity of Rackham and Gun Cays



Photo #5: Dumping ground and south channel



Photo #6: Sediment trap locations at Rackham Cay – June 15, 2002